


Murray City General Plan Natural and Environmental Conditions: Generalized Development Suitability Analysis



Generally Suitable For Development



Generally Unsuitable For Development*



Soils



Wetlands



100 Year Flood Plain



Steep Slopes



Jordan River
Meander Corridor



CERCLIS Site

*For planning and general identification purpose only. Specific site development will require detailed analysis and review. Actual site conditions may differ from those shown on plan.

Sources:

Soils: Soils analysis was based on information from 1974 Soil Survey of Salt Lake Area, Utah. United States Department of Agriculture, Soil Conservation Service. Digital Maps for this survey were obtained from the Utah State Automated Geographic Reference Center, State Geographic Information Database in conjunction with the Soil Survey Geographic Database (SSURGO). WWW.AGRC.GOV/SGID.
CERCLIS: Department of Environmental Quality.
Jordan River Meander Corridor: Salt Lake County Flood Control.
100 Year Floodplain: September 2001 Flood Insurance Rate Maps, Salt Lake County.

— Rail Line
- - - Municipal Boundary

0' 600' 1200' 2400'



NORTH

Map 7-2

JUNE 2003



MURRAY
PUBLIC
SERVICES



LANDMARK
DESIGN

INCORPORATED

LANDSCAPE ARCHITECTURE
AND LAND PLANNING
1854 HIGHLAND DRIVE
SALT LAKE CITY
UTAH 84108
PHONE (801) 474-3300
FAX (801) 474-3303